
Contents

Preface	vii	6.2	Subsurface porosity	186	
Dedication	ix	6.3	Growth of gas pores	195	
Introduction	xi	6.4	Blowholes	200	
1.	<i>The melt</i>	1	7.	<i>Solidification shrinkage</i>	205
1.1	Reactions of the melt with its environment	2	7.1	General shrinkage behaviour	205
1.2	Transport of gases in melts	10	7.2	Solidification shrinkage	206
1.3	Surface film formation	12	7.3	Feeding criteria	210
2.	<i>Entrainment</i>	17	7.4	Feeding – the five mechanisms	212
2.1	Entrainment defects	20	7.5	Initiation of shrinkage porosity	222
2.2	Entrainment processes	31	7.6	Growth of shrinkage pores	226
2.3	Furling and unfurling	54	7.7	Final forms of shrinkage porosity	227
2.4	Deactivation of entrained films	61			
2.5	Soluble, transient films	63	8.	<i>Linear contraction</i>	232
2.6	Detrainment	64	8.1	Uniform contraction	232
2.7	Evidence for bifilms	64	8.2	Non-uniform contraction (distortion)	237
2.8	The significance of bifilms	67	8.3	Hot tearing	242
3.	<i>Flow</i>	70	8.4	Cold cracking	258
3.1	Effect of surface films on filling	70	8.5	Residual stress	259
3.2	Effect of entrained films on filling	73			
3.3	Fluidity (maximum fluidity length) L_f	74	9.	<i>Structure, defects and properties of the finished casting</i>	267
3.4	Continuous fluidity	95	9.1	Grain size	267
3.5	Glossary of symbols	98	9.2	Dendrite arm spacing	270
4.	<i>The mould</i>	99	9.3	Compact defects	275
4.1	Inert moulds	99	9.4	Planar defects	279
4.2	Aggregate moulds	100	9.5	Effects of defects on properties of castings	282
4.3	Mould atmosphere	105	9.6	The statistics of failure	301
4.4	Mould surface reactions	111			
4.5	Metal surface reactions	114	10.	<i>Processing</i>	306
5.	<i>Solidification structure</i>	117	10.1	Impregnation	306
5.1	Heat transfer	117	10.2	Hot isostatic pressing	306
5.2	Development of matrix structure	129	10.3	Working (forging, rolling and extrusion)	309
5.3	Segregation	139	10.4	Machining	309
5.4	Aluminium alloys	147	10.5	Painting	310
5.5	Cast irons	156			
5.6	Steels	167	11.	<i>Environmental interactions</i>	311
6.	<i>Gas porosity</i>	178	11.1	Internal oxidation	311
6.1	Nucleation of gas porosity	178	11.2	Corrosion	313
References					318
Index					329