

# Table of Contents

<b>Preface to the First Edition</b> .....	v
<b>Preface to the Second Edition</b> .....	vi
<b>Acknowledgments</b> .....	viii
<b>Introduction</b> .....	ix
<b>Chapter 1 History of Clinker Microscopy</b> .....	1
Photomicrographs of Aspdin Paste .....	1
<b>Chapter 2 Sampling and Sample Storage</b> .....	7
Sampling .....	7
Sample Storage .....	8
Storage of Prepared Specimens .....	8
<b>Chapter 3 Stains and Etches</b> .....	11
Aluminates and Free Lime .....	11
Silicates .....	12
Calcium Fluoroaluminate .....	14
Examination of Stained Cement .....	15
Photomicrographs of Effects of Stains and Etches .....	16
<b>Chapter 4 Preparation of Polished Sections, Thin Sections, and Particle Mounts</b> .....	19
Basic Steps for Rapid Polished Section Preparation .....	20
Encapsulation, Impregnation, and Particle Mounting .....	21
Encapsulation and Impregnation .....	21
Sawing, Grinding, and Polishing .....	22
Isomet™ and Minimet™ Method .....	22
Use of Horizontal Rotary Grinder/Polisher .....	23
Harris's Technique .....	24
Thin Sections .....	25
Techniques with Hyrax™ and Meltmount™ .....	26
Particle Mounts on Thin Epoxy Film .....	27
<b>Chapter 5 Microscopic Characteristics of Clinker Phases</b> .....	29
Alite .....	30
Belite .....	32
Comments on Belite Classification and Polymorphic Varieties .....	34
Tricalcium Aluminate .....	36
Alkali Aluminate .....	37
Ferrite .....	37
Free Lime .....	38
Periclase .....	39
Alkali Sulfates .....	39
Miscellaneous Phases .....	40
<b>Chapter 6 Ono's Method—History, Explanation, and Practice</b> .....	43
History of Ono's Theories of Kiln Control Through Microscopy .....	43
The Ono Method .....	46
Alite Size .....	47
Photomicrographs Illustrating Ono's Method .....	48
Alite Birefringence .....	50

Belite Size .....	52
Belite Color .....	52
Use of Ono's Table to Interpret Kiln Conditions and Formula to Predict 28-day Mortar-Cube Strength .....	52
Additional Comments on the Ono Method and Recent Research .....	55
Alite Birefringence .....	55
Alite Size .....	57
Belite Color .....	59
<b>Chapter 7 Microscopical Interpretation of Clinkers</b> .....	63
Photomicrographs of General Features of Clinkers .....	68
Photomicrographs of Alite .....	79
Photomicrographs of Belite .....	88
Photomicrographs Illustrating the Matrix .....	104
Photomicrographs of Free Lime .....	110
Photomicrographs of Periclase .....	114
Photomicrographs of Miscellaneous Phases .....	117
<b>Chapter 8 Misinterpretations in Clinker Microscopy</b> .....	121
Photomicrographs of Artifacts .....	122
<b>Chapter 9 Scanning Electron Microscopy</b> .....	127
Scanning Electron Microscopy .....	129
<b>Chapter 10 Microscopical Examination of Portland Cement Raw Materials</b> .....	139
Selected Literature Review .....	139
Raw Material Examination .....	142
Petrographic Identification of Raw Feed Constituents .....	142
Feed Particle Classification .....	143
Application of F. L. Smidth's Burnability Equations .....	144
Sample Preparation and Method of Counting .....	147
Sample Preparation .....	147
Insoluble Residues .....	147
Counting Method .....	147
Thin-Section and Half-Section Methods for Raw Feeds .....	148
Half-Sections .....	150
Organic and Inorganic Stains for Raw Feed Mineral Identification .....	150
Stain Technique No. 1 .....	150
Stain Technique No. 2 .....	151
Stain Technique No. 3 .....	151
Photomicrographs of Portland Cement Raw Materials .....	153
<b>Chapter 11 Recommended Formats and Materials</b> .....	163
Suggested Format for Detailed Clinker Examination .....	163
Extraction Techniques for Concentration of Clinker Silicates and Matrix .....	166
Quantitative Microscopy .....	167
Microscopical Equipment, Supplies, and Thin Section Services .....	169
<b>Chapter 12 Conclusions</b> .....	173
<b>References</b> .....	177
<b>Glossary</b> .....	193
<b>Author Index</b> .....	195
<b>Subject Index</b> .....	197